



DEPARTMENT OF THE NAVY  
MILITARY SEALIFT COMMAND  
471 EAST C STREET  
NORFOLK VA 23511-2419

4490  
Ser N7/252  
15 Apr 25

From: Commander, Military Sealift Command  
To: Oscar Björlin, Majnabbe Motor Diesel Service AB

Subj: QUALIFICATION OF MAJNABBE MOTOR DIESEL SERVICE AB AND SWESERV AB TO PROVIDE PARTS AND SERVICE SUPPORT FOR WARTSILA TYPE WN25 ENGINES AND ALL NOHAB ENGINES

Ref: (a) COMSC Instruction 4490.1C

1. Reference (a) establishes Military Sealift Command (MSC) policy and procedures for qualification requirements in the procurement of items critical to safety and the modification, repair and overhaul of those items assigned to Military Sealift Command vessels. The Instruction designates the MSC Engineering Director as the Design Control Activity (DCA) responsible to ensure that the design, production and performance standards are met for ship critical safety items. The instruction further assigns responsibility to the DCA to establish qualification requirements and to qualify and identify vendors that meet the criteria and standards for ship critical safety items.

2. Majnabbe Motor Diesel Service AB (MMAB) and SweServ AB requested biennial reevaluation of their qualification (originally issued 2 April 2020) and submitted all required information. SweServ is the wholly-owned service branch of MMAB. An MSC N7 Engineering DCA evaluation team reviewed that information and determined that MMAB and SweServ AB meet the relevant qualification criteria for parts, maintenance and repair services on Wartsila WN25 and all NOHAB diesel engines.

3. MMAB and SweServ AB are deemed qualified to provide OEM-equivalent parts, maintenance and repair services on MSC ships for Wartsila MN25 and all NOHAB diesel engines. This qualification must be re-evaluated no later than 24 months from the date of this letter. Within its sole discretion, MSC may revoke qualification at any time if MMAB and SweServ AB fail to provide quality maintenance and repair services, or if MMAB and SweServ AB are unable to sustain the capabilities required in reference (a).

4. The MSC point of contact is Benjamin Hawbaker, ph: (757)341-6211; email: msc\_nonoem\_qual@us.navy.mil.

  
Andrew Busk  
Engineering Director