



DEPARTMENT OF THE NAVY  
COMMANDER MILITARY SEALIFT COMMAND  
471 EAST C STREET  
NORFOLK VA 23511-2419

4490  
Ser N7/ 636  
28 OCT 24

From: Commander, Military Sealift Command

To: David Santamaria, President, Motor-Services Hugo Stamp, Inc.

Subj: QUALIFICATION OF MOTOR-SERVICES HUGO STAMP, INC. TO PROVIDE SERVICE AND REPAIR SUPPORT FOR FAIRBANKS MORSE, COLT PIELSTICK, MAN, WARTSILA, BERGEN AND CATERPILLAR/MAK MARINE DIESEL ENGINES AND ABB TURBOCHARGERS

Ref: (a) COMSC Instruction 4490.1C

1. Reference (a) establishes Military Sealift Command (MSC) policy and procedures for qualification requirements in the procurement of items critical to safety and the modification, repair and overhaul of those items assigned to Military Sealift Command vessels. The Instruction designates the MSC Engineering Director as the Design Control Activity (DCA) responsible to ensure that the design, production and performance standards are met for ship critical safety items. The instruction further assigns responsibility to the DCA to establish qualification requirements and to qualify and identify vendors that meet the criteria and standards for ship critical safety items.
2. Motor-Services Hugo Stamp, Inc. requested biennial reevaluation of their qualification (originally issued 25 January 2022) and submitted all required information. An MSC N7 Engineering DCA evaluation team reviewed that information and determined that Motor-Services Hugo Stamp, Inc. meets the relevant qualification criteria for maintenance and repair services on Fairbanks Morse, Colt Pielstick, MAN, Wartsila Bergen and Caterpillar/MaK diesel engines. In addition, MSHS is qualified to provide maintenance and repair services for ABB diesel engine turbochargers.
3. Motor-Services Hugo Stamp, Inc. is deemed qualified to provide OEM-equivalent maintenance and repair services on MSC ships for Fairbanks Morse, Colt Pielstick, MAN, Wartsila Bergen and Caterpillar/MaK diesel engines, as well as ABB turbo-chargers. This qualification must be re-evaluated no later than 24 months from the date of this letter. Within its sole discretion, MSC may revoke qualification at any time if Motor-Services Hugo Stamp, Inc. fails to provide quality maintenance and repair services, or if Motor-Services Hugo Stamp, Inc. is unable to sustain the capabilities required in reference (a).
4. The MSC point of contact is Benjamin Hawbaker, ph: (757)341-6211; email: [msc\\_nonoem\\_qual@us.navy.mil](mailto:msc_nonoem_qual@us.navy.mil).

A. BUSK  
Engineering Director