



DEPARTMENT OF THE NAVY  
COMMANDER MILITARY SEALIFT COMMAND  
471 EAST C STREET  
NORFOLK VA 23511-2419

4490  
Ser N7/778  
28 Nov 23

From: Commander, Military Sealift Command  
To: Alan Wiley, Coyote Technical Services, LLC

Subj: QUALIFICATION OF COYOTE TECHNICAL SERVICES, LLC TO PROVIDE GENERAL ELECTRIC (GE) CONTROL AND MONITORING, GENERATOR CONTROL, DC PROPULSION DRIVE, AND POWER DISTRIBUTION SYSTEMS SERVICE AND REPAIR SUPPORT

Ref: (a) COMSC Instruction 4490.1C

1. Reference (a) establishes Military Sealift Command (MSC) policy and procedures for qualification requirements in the procurement of items critical to safety and the modification, repair and overhaul of those items assigned to Military Sealift Command vessels. The Instruction designates the MSC Engineering Director as the Design Control Activity (DCA) responsible to ensure that the design, production and performance standards are met for ship critical safety items. The instruction further assigns responsibility to the DCA to establish qualification requirements and to qualify and identify vendors that meet the criteria and standards for ship critical safety items.
2. Coyote Technical Services, LLC requested biennial reevaluation of their qualification (originally issued 19 Feb 2019) and submitted all required information. An MSC N7 Engineering DCA evaluation team reviewed that information and determined that Coyote Technical Services, LLC meets the relevant qualification criteria for maintenance and repair services on GE control and monitoring, generator control, DC propulsion drive, and power distribution systems.
3. Coyote Technical Services, LLC is deemed qualified to provide OEM-equivalent parts and maintenance and repair services on MSC ships for GE control and monitoring, generator control, DC propulsion drive, and power distribution systems. This qualification must be re-evaluated no later than 24 months from the date of this letter. Within its sole discretion, MSC may revoke qualification at any time if Coyote Technical Services, LLC fails to provide quality maintenance and repair services, or if Coyote Technical Services, LLC is unable to sustain the capabilities required in reference (a).
4. The MSC point of contact is Benjamin Hawbaker, ph: (757)341-6211; email: [msc\\_nonoem\\_qual@us.navy.mil](mailto:msc_nonoem_qual@us.navy.mil).

A. BUSK  
Engineering Director